

## Care & Repair



Performance in FRP

OPTIFLAM



# POLYDET®

## Care & Repair

### General

Glass fiber-reinforced composites are durable but will require regular maintenance to preserve their appearance and extend their lifespan.



### Keep it Clean


Remove light to moderate dirt like dust, salt, mud, stains, light oxidation.

#### Wash

1. Clean the surface with a mild liquid detergent.
2. Avoid abrasive cleaners, dirty brushes, or any tools that could scratch the surface.
3. Rinse thoroughly with clear water to remove dirt, dust, and other residues.

#### Product Recommendation

- **MEGUIAR'S M54** Gel Wash highly concentrated formula that gently cleans & protects the wax layer
- **MEGUIAR'S M50** Cleaner Wax One Step Liquid combines cleaning & protection in one step, removing light oxidation and scratches



### Keep it Shiny

Remove heavy dirt, oxidation, weathering and minor scratches.

#### Polishing & Wax

1. Polish to smooth the surface and maintain its original shine.
2. Apply protective wax to seal the surface, making it more resistant to dirt, scratches, sunlight and moisture.

#### Products Recommendation

- **MEGUIAR'S M67** One Step Compound Aggressive Cleaner plus Polish cleans, protects, and removes light oxidation & scratches in one step
- **MEGUIAR'S M45** High Gloss Polish restores gloss to surface
- **MEGUIAR'S M56** Pure Wax Carnauba / **M59** Quick Wax Marine reliable protection against UV rays and corrosion

Fiberglass-reinforced laminate offers enhanced strength and durability. Its surface is coated with a protective gelcoat, providing exceptional resistance to UV rays & scratches, ensuring long-lasting performance even in harsh environmental conditions.



## Keep it Repaired

Minor scratches can be repaired using rubbing compound, followed by waxing. For extensive damage, consult a professional for proper restoration.

- avoid using pressure washers at close range, as they can damage the surface
- avoid aggressive chemicals like chlorine or solvents



## Storage

Proper storage and winterization are essential for preserving quality, especially during inactivity or harsh weather conditions. Preventive measures protect surface and avoid moisture damage.

- thoroughly clean the surface before storage & ensure it is completely dry
- protect the surface from sun exposure and moisture
- regularly check for debris such as leaves or dirt buildup
- protect with a cover if unused for longer periods



contact us!

# POLYDET®

 **OPTIPLAN**

Member of  **senata** Group

Am Johannisberg 9 - 13  
08606 Oelsnitz  
Germany

+49 37421 494 0  
[sales@optiplan.eu](mailto:sales@optiplan.eu)  
[www.optiplan.eu](http://www.optiplan.eu)